

BNC INFORMATICS, SAMTSE

1a. Price and Delivery Schedule for Goods: Goods Manufactured outside Bhutan (Form e-LG-4a)

Line Item No.	Description of Item	Unit of Measurement	Quantity	Period of Delivery	Currency	Amount per line item
I	PhotoCopy Machine parts:					
1.0	Power supply board change	Each	1.000	30.0	BTN	6000.000
2.0	Main motherboard change	Each	1.000	30.0	BTN	12000.000
3.0	High voltage transfer (HVT) change	Each	1.000	30.0	BTN	2000.000
4.0	Power supply board repairing	Each	1.000	30.0	BTN	3500.000
5.0	Main motherboard repairing	Each	1.000	30.0	BTN	3400.000
6.0	High voltage transfer (HVT) repairing	Each	1.000	30.0	BTN	1500.000
7.0	Image processing (IP) board	Each	1.000	30.0	BTN	6000.000
8.0	Scanning unit	Each	1.000	30.0	BTN	4500.000
9.0	Scanning cable	Each	1.000	30.0	BTN	1500.000
10.0	Main motor	Each	1.000	30.0	BTN	4500.000
11.0	Drum unit assembly	Each	1.000	30.0	BTN	8000.000
12.0	Drum changed	Each	1.000	30.0	BTN	3500.000
13.0	D/C Blade changed	Each	1.000	30.0	BTN	1200.000
14.0	Laser unit	Each	1.000	30.0	BTN	3500.000
15.0	Laser gun (inside laser unit)	Each	1.000	30.0	BTN	2900.000
16.0	Fuser unit assembly changed	Each	1.000	30.0	BTN	4500.000
17.0	Pressure roller changed	Each	1.000	30.0	BTN	1800.000
18.0	Fixing film/fuser film/teflon sleeve	Each	1.000	30.0	BTN	2200.000
19.0	Fixing unit	Each	1.000	30.0	BTN	2300.000
20.0	Paper Pick up assembly repairing	Each	1.000	30.0	BTN	600.000
21.0	Transfer section	Each	1.000	30.0	BTN	800.000
22.0	Cassette or paper tray	Each	1.000	30.0	BTN	1800.000
23.0	Solenoid or relay switch	Each	1.000	30.0	BTN	1500.000
24.0	Regulation clutch	Each	1.000	30.0	BTN	1200.000
25.0	Post cript clutch	Each	1.000	30.0	BTN	1300.000
26.0	Developer assembly Changed	Each	1.000	30.0	BTN	5900.000
27.0	Paper exit sensor	Each	1.000	30.0	BTN	700.000
28.0	Shifter motor	Each	1.000	30.0	BTN	1300.000
29.0	Developer powder DV116	Each	1.000	30.0	BTN	3500.000
30.0	Carriage assembly	Each	1.000	30.0	BTN	2900.000
31.0	Lower heat roller kit	Each	1.000	30.0	BTN	2900.000
32.0	MC unit	Each	1.000	30.0	BTN	4500.000
33.0	upper exit tray saperator	Each	1.000	30.0	BTN	980.000
34.0	Servicing charges inclusive of installation Repairing & troubleshooting)	Each	1.000	30.0	BTN	900.000
II	Printer Parts:					
1.0	ECU unit	Each	1.000	30.0	BTN	3200.000
2.0	scanner unit	Each	1.000	30.0	BTN	1800.000
3.0	Power supply board changed	Each	1.000	30.0	BTN	4500.000

4.0	Power supply board repaired	Each	1.000	30.0	BTN	1980.000
5.0	Encoder clock sensor	Each	1.000	30.0	BTN	2200.000
6.0	Post script clutch	Each	1.000	30.0	BTN	900.000
7.0	Registration clutch	Each	1.000	30.0	BTN	800.000
8.0	Shifter motor	Each	1.000	30.0	BTN	1300.000
9.0	Timing belt	Each	1.000	30.0	BTN	2300.000
10.0	RD assembly	Each	1.000	30.0	BTN	3200.000
11.0	Head cable	Each	1.000	30.0	BTN	670.000
12.0	Saperation solenoid	Each	1.000	30.0	BTN	1200.000
13.0	Tower motor	Each	1.000	30.0	BTN	1200.000
14.0	Pressure Roller	Each	1.000	30.0	BTN	890.000
15.0	Fuser film	Each	1.000	30.0	BTN	900.000
16.0	Scanning data cable	Each	1.000	30.0	BTN	500.000
17.0	Paper exit sensor	Each	1.000	30.0	BTN	980.000
18.0	Fuser unit paper delivery roller	Each	1.000	30.0	BTN	670.000
19.0	paper delivery sensor	Each	1.000	30.0	BTN	890.000
20.0	Paper Pickup roller	Each	1.000	30.0	BTN	560.000
21.0	Main formatter logic card	Each	1.000	30.0	BTN	5600.000
22.0	Duplex motor	Each	1.000	30.0	BTN	2450.000
23.0	Paper feed solenoid	Each	1.000	30.0	BTN	760.000
24.0	Document cover sensor	Each	1.000	30.0	BTN	450.000
25.0	Thermostate	Each	1.000	30.0	BTN	450.000
26.0	Mannual feed empty sensor	Each	1.000	30.0	BTN	670.000
27.0	Paper switching solenoid	Each	1.000	30.0	BTN	785.000
28.0	Paper exit sensor	Each	1.000	30.0	BTN	687.000
29.0	Home position sensor	Each	1.000	30.0	BTN	670.000
30.0	Printer Casing	Each	1.000	30.0	BTN	659.000
31.0	Servicing charges inclusive of installation Repairing & troubleshooting)	Each	1.000	30.0	BTN	690.000
						150091.000

